

General Environmental Incident Summary

Incident: 1859 **Date/Time Notice:** 1/28/2013 1430 **DEM Incident No:**
Responsible Party: Rose Rock Midstream LP
Date Incident: 1/28/2013 **Time Incident:** 1130 **Duration:** 8 hours
County: Williams **Twp:** 154 **Rng:** 95 **Sec:** 6 **Qtr:** SE SW
Lat: 48.19000 **Long:** -102.94690 **Method:** Derived from TRS
Location Description: 35 miles east on of Williston on Hwy 1804, then South on County Road 21
1/2 mile to location

Submitted By: Lance King **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Dick Clary
3030 Northwest Expressway
Oklahoma City, OK 73112

Distance Nearest Occupied Building: 0 Feet

Type of Incident: chain came off truck tire and damaged vavle

Description of Released Contaminant: Crude oil

Volume Spilled: 8.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Tire chain broke came and damaged truck vavle

Risk Evaluation:

N/a

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Crude oil leaking on to gravel road surface from damaged truck vavle

Action Taken or Planned:

Oil is being removed from road surface by Vac Truck

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/28/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release happened on public road. Please follow-up and determine whether clean up is complete.

Date: 1/29/2013 **Status:** Reviewed - Follow-up Required

Author: Radig, Scott

Updated Volume:

Notes:

Received call from Lance King to correct the location. Spill was in Twp 154, Rng 95, Section 6. Quarter-Quarter section is the same.

Date: 2/1/2013 **Status:** Inspection

Author: Roberts, Kris

Updated Volume:

Notes:

Roberts and Miller inspected. Release location on SE corner of Williams Co Rd 21 and Lease road, 1/4 mile south of 1804. Indication of loss and vacuuming apparent, but no soil removal or scraping. Drainage from location is to the east via road ditch into small depression that doesn't appear to drain away. Should review this location in the spring of 2013 to determine vegetation recovery, or need for further work

Date: 2/7/2013 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

11:25 AM 2/7/13

No action taken same as 2/1/13, check back again in spring to see if vegetation in ditch survived spill.

Date: 4/15/2015 **Status:** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

According to the inspections and note on the 2/1/13 update, this site and incident needs to be rechecked this spring.